


# XFlash Installation Description




**Software is protected by Wibu CodeMeter.  
A valid license is necessary (Dongle) !**  
(see documentation "[Wibu Codemeter Dongle](#)")

Start **XFlashi.exe** manually or press the **Install XFlash** button:


The installation set installs the Samtec ActiveX components and the XFlash User Interface.



>> Press Button **Next** to continue or **Cancel** to abort the installation.



>> Press Button **Next** to continue or **Cancel** to abort the installation.




>> Accept the license terms and press button **Next** to continue or **Cancel** to abort the installation.

If you do not agree to the license statement, you have to abort the installation !

Select the installation options now


Use the default settings "**XFlash**" User Interface and "**Samtec SamdiaX ActiveX**" component:



XFlash installation needs nearly **150 MB** free disk space on the local harddisk.

>> Press button "**Install**" to continue or **Cancel** to abort the installation.

... installation starts copy files ....




>> On “non Bosch” computers, the Wibu Codemeter Runtime software will be installed. This software is necessary to handle the licensing on the connected dongle:



>> the correct installation is shown by the “codemeter” icon in the system menu:




>> plug on your License Dongle:



>> **The software does not work without valid License Dongle !! <<**

After correct installation you get a success message:



Thats it ...

**The complete installation needs about 150 MB free harddisk space.**